

Trhací myly

S plochou hlavou AI/St



dlk - hřídek A11g3,5
tm - ocet ztrhovaná

| K | hřezel mm | L mm | A mm | D mm | B mm | W mm | V ° |
|-------|--------------|-----------|---------|---------|---------|---------|--------|
| 34 | 1 | 0,8-1,0 | 0,0 | 0,8 | 0,0 | 100 | 400 |
| | 4 | 2,0-4,0 | | | | | |
| | 6 | 4,0-6,0 | | | | | |
| | 8 | 6,0-7,0 | 0,0 | 0,8 | 0,0 | 100 | 400 |
| | 11 | 7,0-8,0 | | | | | |
| 38 | 6 | 1,0-1,0 | | | | | |
| | 7 | 2,0-2,0 | | | | | |
| | 8 | 3,0-3,0 | | | | | |
| | 9 | 4,0-4,0 | | | | | |
| | 10 | 4,0-4,0 | | | | | |
| | 11 | 4,0-4,0 | 0,0 | 0,8 | 0,0 | 100 | 400 |
| | 12 | 6,0-6,0 | | | | | |
| | 13 | 8,0-7,0 | | | | | |
| | 14 | 8,0-8,0 | | | | | |
| | 15 | 10,0-10,0 | | | | | |
| 52-34 | 3,3 | 1,0-1,0 | 0,0 | 1,0 | 0,0 | 1100 | 1000 |
| | 4,4 | 2,0-2,0 | | | | | |
| | 5,5 | 3,0-3,0 | | | | | |
| | 6,6 | 4,0-4,0 | | | | | |
| | 7,7 | 5,0-5,0 | | | | | |
| | 8,8 | 6,0-6,0 | 0,0 | 1,0 | 0,0 | 1100 | 1000 |
| | 9,9 | 7,0-7,0 | | | | | |
| | 11,0 | 8,0-8,0 | | | | | |
| | 12,1 | 10,0-10,0 | | | | | |
| | 13,2 | 12,0-12,0 | | | | | |
| 52-34 | 3,3 | 1,0-1,0 | 0,0 | 1,0 | 0,0 | 1100 | 1000 |
| | 4,4 | 2,0-2,0 | | | | | |
| | 5,5 | 3,0-3,0 | | | | | |
| | 6,6 | 4,0-4,0 | | | | | |
| | 7,7 | 5,0-5,0 | | | | | |
| | 8,8 | 6,0-6,0 | 0,0 | 1,0 | 0,0 | 1100 | 1000 |
| | 9,9 | 7,0-7,0 | | | | | |
| | 11,0 | 8,0-8,0 | | | | | |
| | 12,1 | 10,0-10,0 | | | | | |
| | 13,2 | 12,0-12,0 | | | | | |

Trhací myly

s plochou hlavou AI/St



dlk - hřídek A11g 3,5
tm - ocet ztrhovaná

| K | hřezel mm | L mm | A mm | D mm | B mm | W mm | V ° |
|----|--------------|-----------|---------|---------|---------|---------|--------|
| 34 | 1 | 1,0-2,0 | | | | | |
| | 7 | 2,0-4,0 | | | | | |
| | 9 | 3,0-5,0 | | | | | |
| | 11 | 5,0-7,0 | 0,7 | 1,0 | 1,0 | 1070 | 900 |
| | 12 | 7,0-8,0 | | | | | |
| 41 | 6 | 1,0-1,0 | | | | | |
| | 7 | 2,0-2,0 | | | | | |
| | 8 | 3,0-3,0 | 0,0 | 1,0 | 1,0 | 1000 | 1070 |
| | 9 | 4,0-4,0 | | | | | |
| | 10 | 5,0-5,0 | | | | | |
| | 11 | 6,0-6,0 | 0,0 | 1,0 | 1,0 | 1000 | 1070 |
| | 12 | 7,0-7,0 | | | | | |
| | 13 | 8,0-8,0 | | | | | |
| | 14 | 9,0-9,0 | | | | | |
| | 15 | 10,0-10,0 | | | | | |
| 47 | 6 | 1,0-1,0 | 0,0 | 1,0 | 1,0 | 1000 | 1070 |
| | 7 | 2,0-2,0 | | | | | |
| | 8 | 3,0-3,0 | 0,0 | 1,0 | 1,0 | 1000 | 1070 |
| | 9 | 4,0-4,0 | | | | | |
| | 10 | 5,0-5,0 | | | | | |
| | 11 | 6,0-6,0 | 0,0 | 1,0 | 1,0 | 1000 | 1070 |
| | 12 | 7,0-7,0 | | | | | |
| | 13 | 8,0-8,0 | | | | | |
| | 14 | 9,0-9,0 | | | | | |
| | 15 | 10,0-10,0 | | | | | |

Trhací myly

S plochou hlavou AI/St



dlk - hřídek A11g3,5
tm - ocet ztrhovaná

| K | hřezel mm | L mm | A mm | D mm | B mm | W mm | V ° |
|----|--------------|-----------|---------|---------|---------|---------|--------|
| 43 | 1 | 1,0-2,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 7 | 2,0-4,0 | | | | | |
| | 8 | 3,0-4,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 9 | 4,0-5,0 | | | | | |
| | 10 | 5,0-6,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 11 | 6,0-7,0 | | | | | |
| | 12 | 7,0-8,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 13 | 8,0-9,0 | | | | | |
| | 14 | 9,0-10,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 15 | 10,0-11,0 | | | | | |
| 48 | 1 | 1,0-2,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 7 | 2,0-4,0 | | | | | |
| | 8 | 3,0-4,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 9 | 4,0-5,0 | | | | | |
| | 10 | 5,0-6,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 11 | 6,0-7,0 | | | | | |
| | 12 | 7,0-8,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 13 | 8,0-9,0 | | | | | |
| | 14 | 9,0-10,0 | 0,0 | 1,0 | 1,0 | 2040 | 2000 |
| | 15 | 10,0-11,0 | | | | | |

Trhací myly

s plochou hlavou AI/St



dlk - hřídek A11g3,5
tm - ocet ztrhovaná

| K | hřezel mm | L mm | A mm | D mm | B mm | W mm | V ° |
|----|--------------|-----------|---------|---------|---------|---------|--------|
| 58 | 1 | 1,0-2,0 | | | | | |
| | 7 | 2,0-4,0 | | | | | |
| | 8 | 3,0-4,0 | 0,0 | 1,0 | 1,0 | 2040 | 2100 |
| | 9 | 4,0-5,0 | | | | | |
| | 10 | 5,0-6,0 | 0,0 | 1,0 | 1,0 | 2040 | 2100 |
| | 11 | 6,0-7,0 | | | | | |
| | 12 | 7,0-8,0 | 0,0 | 1,0 | 1,0 | 2040 | 2100 |
| | 13 | 8,0-9,0 | | | | | |
| | 14 | 9,0-10,0 | 0,0 | 1,0 | 1,0 | 2040 | 2100 |
| | 15 | 10,0-11,0 | | | | | |
| 68 | 1 | 1,0-2,0 | | | | | |
| | 7 | 2,0-4,0 | | | | | |
| | 8 | 3,0-4,0 | 0,0 | 1,0 | 1,0 | 4700 | 2040 |
| | 9 | 4,0-5,0 | | | | | |
| | 10 | 5,0-6,0 | 0,0 | 1,0 | 1,0 | 4700 | 2040 |
| | 11 | 6,0-7,0 | | | | | |
| | 12 | 7,0-8,0 | 0,0 | 1,0 | 1,0 | 4700 | 2040 |
| | 13 | 8,0-9,0 | | | | | |
| | 14 | 9,0-10,0 | 0,0 | 1,0 | 1,0 | 4700 | 2040 |
| | 15 | 10,0-11,0 | | | | | |

Trhací myly

standardní s plochou hlavou



hlavní: dlk - hřídek A11g3,5
tm - ocet ztrhovaná

| K | hřezel mm | L mm | A mm | D mm | B mm | W mm | V ° |
|----|--------------|---------|---------|---------|---------|---------|--------|
| 88 | 1 | 1,0-2,0 | | | | | |
| | 7 | 2,0-4,0 | | | | | |
| | 8 | 3,0-4,0 | 0,0 | 1,0 | 1,0 | 8000 | 6000 |
| | 9 | 4,0-5,0 | | | | | |
| | 10 | 5,0-6,0 | 0,0 | 1,0 | 1,0 | 8000 | 6000 |